Testing Laboratories, Inc. 940 South Harney Street. Seattle. Washington 98108 (206) 767-5060



85135

July 3, 1984

PO #A-2965

LABORATORY NO.

DATE

Chemistry Microbiology and Technical Services

CLIENT

Alaskan Copper & Brass 3200-6th Ave. S. Seattle, WA 98134 ATTN: Gary

REPORT ON

SEDIMENT

SAMPLE IDENTIFICATION

Sample submitted 6-21-84 and identified as shown below:

Tank Bottom - 3200 6-21-84

TESTS PERFORMED AND RESULTS:

Sample was analyzed in accordance with 40 CFR 261.24 for EP Toxicity with results as follow:

Sample MCL pH, glass electrode at 25°C* 12.9 **

*on liquid phase of sample

concentration, mg/L

	Sample	MCL
Arsenic	L/0.2	5.0
Barium	. ÷ • 5	100.
Cadmium	L/0.02	1.0
Chromium	.8	5.0
Lead	L/0.2	5.0
Mercury	L/0.005	0.2
Selenium	L/0.2	1.0
Silver	L/0.1	5.0



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.





Chemistry, Microbiology, and Technical Services

PAGE NO.

2

Alaskan Copper & Brass

LABORATORY NO.

85135

Key

MCL = Maximum Contamination Level allowed per regulation.

L/ = Less than

** = pH must fall between 2.0 and 12.5 per regulation.

Respectfully submitted,

Laucks Testing Laboratories, Inc.

M. Owens

JMO:rtv



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.